ame, Address City, County, ZIP : rnald Environmental Management Project 00 Willey Road milton OH45013940

Station Code:

Reported Date (Month Year):

August 2001

Application:

09/19/2001

1I000004*FD Page 1 of 4

Sampling Station Description : FINAL OUTFALL - PARSHALL FLUME

3883

			3 for Grab Sample F	Reporting Lab :		Analyst :	
) - Ent	ter frequency of s	ampling					
(1)	2	2	2	2] 2	2	2
(2)	998	998	998	998	998	998	998
	(80082)	(01094)	(01113)	(01114)	(01118)	(01119)	(01055)
	CBOD 5 day mg/l	Zinc, Total Recoverable	Cadmium, Total Recoverable	Lead, Total Recoverable	Chromium, Total Recoverable	Copper, Total Recoverable	Manganese, Tota (Mn)
у	9/ -	ug/l	ug/1	ug/l	ug/1	ug/l	ug/l
	AA	AA	AA	1.78	2.1	· AA	47
!					·		
		5.3	AA	3.49	2.1	AA	
							
,			·		· · · · · .	·	
;	AA	AA ·	AA	1.94	1.3	1.7	64.4
,							
3	AA	AA	AA	· AA	1.6	2.1	61.5
						2.1	01.3
+							
<u>' </u>		9.9	AA	8.06		1.7	
		3.3	AA	8.06	2.2	1./	
						*	
	AA	9.9	AA	2.73	3.3	2.7	38.3
<u> </u>		•				* * *	
	AA	AA	AA	AA	AA	4.9	41.1
		AA	2.8	0.94	AA	10.9	
	AA	AA	AA	1 .	AA	12	39.7
						······································	
		3.8	2	1.15	AA	5	
;	AA	AA	AA	1.51	AA	4.4	71.8
\top			-				
	AA	AA	AA	AA	AA	14.7	76.1
				1 1			
+					, ,		
_					<u> </u>		
-	0	30 0		00.7	10.5		430.0
AL 3		28.9	4.8	22.6	12.6	60.1	439.9
	0	2.4083 9.9	0.4	1.8833	1.05	5.0083	54.9875
X	0	9.9	2.8	8.06	3.3	14.7	76.1
w I	13	5.1 · B	11	n		.,1	. 492


dditional Remarks:

I certify under the penalty of law that I have personally examined and am familiar with the information submitted and based on my inquiry of those individuals immediately responsible for obtaining the information, I believe the submitted information is true, accurate and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment.

rm No EPA 4500 (8-91)

MARIY FRA SURI

Date Report Completed: 09/19/2001



Title of Reporter: ARWWP PROJECT MANAGER me, Address City, County, ZIP: nald Environmental Management Project

0 Willey Road milton OH 45013940 Station Code: 001

Reported Date (Month Year):

August 2001

Application: 11000004*FD

09/19/2001

Page 2 of 4

Sampling Station Description: FINAL OUTFALL - PARSHALL FLUME

3883

1) - Enter 1 for Continuous, 2 for Composite, 3 for Grab Sample Reporting Lab: Analyst: 2) - Enter frequency of sampling

44.1		· · · · · · · · · · · · · · · · · · ·			<u> </u>	1	
(1)		2	3	2	3	2	1 000
(2)	998	998	1 (00710)	998	1 (00550)	998	999
	(01074) Nickel, Total	(01079) Silver, Total	(00719) Cyanide, Free	(00530) Total Suspended	(00550) Oil and Grease,	(00610) Nitrogen, Ammonia	pH, Minimum
	Recoverable	Recoverable	mg/l	Solids	Total	(NH3)	s.v.
ay	ug/l	ug/l		mg/l	mg/1	mg/l	
01	1.7	AA	AA	AA	AA	AA	AD
02				2 .			AD .
03	· AA	AA	AA	AA		AA	7.2
)4				AA			7.2
)5				· AA			7.2
06	1.2	AA	AA	· AA	AA	AA :	7.2
)7	,			AA			6.9
80	2.3	0.5	AA	AA	AA	AA	7.2
9				AA			7.1
10				AA			7.1
11	AA	· AA	AA	AA		AA	7.2
12			*	. 4			7.2
13				2.4			7.2
14	2.5	. AA	AA	AA	.AA	AA .	7.2
15				AA			7.2
16	AA	0.22	AA	AA	AA	AA	7.2
17				AA			7.2
8				AA			7.2
19	AA	AA	· AA	AA		. AA	7.2
20	•			AA			7.2
21	AA	AA	AA	AA	AA	AA	7.2
22				AA AA			7.2
23						<u> </u>	7.1
	3.3	0.18	3.3	AA		1.02	7.1
24	AA	0.18	AA	AA		1.02	7.1
25				. 2		1.50	7.1
26	AA	AA .	AA .	AA	AA.	1.59	
27				2			7.1
28	6.1	AA	AA	3.2	AA	2.42	7
29				2.4			7
ВО				AA			7.1
B 1				2.8			7.2
TAL	13.8	0.9	0	20.8	0	5.03	207.3
VG	1.15	0.075	0	0.671	0	0.4192	
ΑX	6.1	0.5	. 0	4	0	2.42	7.2
IIN	0	0	0	0	0	0	0
		<u> </u>					

dditional Remarks:

Name, Address City, County, ZIP: Femald Environmental Management Project

7400 Willey Road Hamilton OH45013940 Station Code:

Reported Date (Month Year):

· August 2001

Application:

09/19/2001

388⁹

Sampling Station Description: FINAL OUTFALL - PARSHALL FLUME

in(1) - Enter 1 for Continuous, 2 for Composite, 3 for Grab Sample Reporting Lab :

in(2) - Enter frequency of sampling

Analyst :

	The frequency of						
(1)	3	3	1	3	1	T 3	3
(2)	1	1	999 \	1	999	1	1
Day	(00010) Water Temperature C	(00300) Dissolved Oxygen mg/l	(00401) pH, Maximum S.U.	(78391) Trichloroethene ug/l	(50050) Flow Rate MGD	(50060) Chlorine, Total Residual mg/l	(39400) Toxaphene, Tota ug/l
01	11.1	8.4	AD		6.018	AA	
02	11.9	· ·	AD		6.108	AA	
03	11.6		7.2		6.251		
04	11.6		7.3		6.379		
05	11.6	8.2	7.3		6.198		
06	12	6.6	7.2		6.634	AA	
07	11.9		7.2		5.998		
80	12.1		7.2	AA	6.354	AA	AA
09	11.7		7.2		6.409	AA	
10	11.4		7.4		6.409		
11	11.3		7.2		6.153		
12	11.6		7.2		3.783		
13	11.3		7.2		6.031		
14	11.2	8.8	7.2		6.103	AA	
15	10.9		7.2		6.03		
16	11.4	7.7	7.2		5.722	. AA	
17	10.6		7.2		5.239		
18	10.8		7.2		5.411		
19	11		7.2		5.681		
20	11.1		7.2		5.443	AA	
21	11.5	7.6	7.2		5.808	AA	
22	12.1		7.2		5.919		
23	12.4		7.2		6.209		
24	12.8		7.2		6.275		,
25	11.1		7.2		6.181		
26	12.8	6.6	7.1		6.348	AA	
27	11.8		7.1	·	6.293	AA	
28	12.3	7.2	7.1		6.407	AA	
29	12.8		7.2		6.3		
30	11.7		8		6.216		
31	11.7		7.4		5.98		· · · · · · · · · · · · · · · · · · ·
OTAL	361.1	61.1	209.9	0	186.29	0	0
AVG	11.6484	7.6375		Ö	6.0094	0	0
MAX	12.8	8.8	8	0	6.634	0	0
MIN	10.6	6.6	0	0	3.783	0	0

Additional Remarks:

Name, Address City, County, ZIP: Femald Environmental Management Project

7400 Willey Road Hamilton OH45013940 Station Code:

Reported Date (Month Year):

August 2001

Application:

09/19/2001

1I000004*FD

Page 4 of 4

Sampling Station Description: FINAL OUTFALL - PARSHALL FLUME

3883

in(1) - Enter 1 for Continuous, 2 for Composite, 3 for Grab Sample Reporting Lab :

in(2) - Enter frequency of sampling

Analyst :

(1)	3	3	3	3	2	·	<u></u>
(2)[1	1	1	1	998		
Day	(34675) 2,3,7,8 TCDD pg/l	(39032) Pentachlorophenol ug/1	(39120) Benzidine, Total ug/l	(99992) Mercury, Total Recoverable ug/l	(00979) Cobalt, Total Recoverable ug/l		
01					0.9	i	
02							
03							
04	. ·						
05							
06	,)		AA		
07							
08	AA	AA	AA	0.00063	AA		
09							
10							
11							
12							
13							
14					AA		
15							
16					AA		
17	·						
18							
19							
20			·				
21					AA		
22		` '.					
23							
24							
25					•		
26	- No. 1 (1)				. AA		
27				,			
28					AA		
29							
30							
31							
OTAL	0	0	0	0.0006	0.9	0	, 0
AVG	Ö	0	0	0.0006	0.1125		
MAX	0	0	0	0.00063	0.9		
MIN	0	0	0	0.00063	0		

Additional Remarks:

ces

OMMENT:

D: CONTINUOUS PH METER WAS OUT OF SERVICE NTIL AUGUST 3RD. GRAB SAMPLES FOR PH WERE OLLECTED SIX TIMES PER DAY.

3883

ame, Address City, County, ZIP: rnald Environmental Management Project Station Code:

Reported Date (Month Year):

Application:

09/19/2001

00 Willey Road milton OH45013940 002 · August 2001 1I000004*FD.

Page 1 of 1

Sampling Station Description: BYPASS MONITORING - SWRB OVERFLOW

3883

			3 for Grab Sample F	Reporting Lab:		Analyst:	
2) - E	nter frequency of s	sampling					
(1)	2	2	3	3	2	3	3
(2)	3	3	1	1	3	1.	1
` '	(01119)	(00530)	(00402)	(00401)	(50050)	(50060)	(99992)
	Copper, Total Recoverable	Total Suspended Solids	pH, Minimum	pH, Maximum	Flow Rate	Chlorine, Total	Mercury, Total Recoverable
Day	ug/l	ug/l	ug/l	ug/l	ug/l	Residual ug/l	ug/l
01	ΑĻ						
02							
03	<u></u>						
04							
05						· · · ·	
06							
07							
08				,			
09							
10				<u> </u>	· · · · · · · · · · · · · · · · · · ·		
11							
12							
13							
1					,		
14		<u> </u>					
15							
16							
17							
18						`	
19							
20						·	
21							
22	-		·				,
23							
24				,	,		
25					· · · · · · · · · · · · · · · · · · ·		
26						`	
27							
28							
29							
30				,			
31			•				
TAL	. 0	0	0	0	0	0	0
VG	0						
IAX	U						

dditional Remarks:

0

ΛIN

I certify under the penalty of law that I have personally examined and am familiar with the information submitted and based on my inquiry of those individuals immediately responsible for obtaining the information, I believe the submitted information is true, accurate and complete. I am aware that there are significant benalties for submitting false information, including the possibility of fine and imprisonment.

rm No EPA 4500 (8-91)

enderly Erra, Suri

Date Report Completed: 09/19/2001



Title of Reporter: ARWWP PROJECT MANAGER amilton OH45013940

4500

ame, Address City, County, ZIP: rnald Environmental Management Project 00 Willey Road

Station Code: 601

Reported Date (Month Year): August 2001

Application:

09/19/2001

1IO00004*FD

Sampling Station Description:

INTERNAL MONITORING STATION - SEWAGE TREATMENT PLANT

Page 1 of 1

3883

(1) - Enter 1 for Continuous, 2 for Composite, 3 for Grab Sample	Reporting Lab:	Analyst:
(2) - Enter frequency of sampling		

						· · · · · · · · · · · · · · · · · · ·	
(1)	2	3	2	2	3	1	
(2)		1	998	998	1	999	
	(80082) CBOD 5 day	(31616) Fecal Coliform	(00530)	(00610)	(00400)	(50050)	
	mg/l	No./100ml	Total Suspended Solids	Nitrogen, Ammonia (NH3)	pH S.U.	Flow Rate MGD	
Эау			mg/l	mg/1			
01	AA		15.2		6.22	0.0508	
02					6.34	0.0161	•
03					6.16	0.048	
04					6.23	0.0543	
05					6.36	0.0458	
06	AA	1	2.4		6.52	0.0168	
07					6.48	0.0548	,
80	AA		5.6	0.2	6.06	0.0535	
09					5.69	0.0265	
10					5.98	0.07114	
11					6.14	0.05486	
12					6.09	0.03508	
13		,	1		6.41	0.0231	
14	AA	1	3.2		6.21	0.02409	
15					5.97	0.0523	
16	AA		5.2		5.63	0.06075	
17					5.65	0.04445	
18					5.67	0.0401	
19					6.3	0.0707	
20					6.74	0.044	:
21	2.8	1	13.6		6.23	0.0493	
22					5.24	0.0507	
23		-	· · · · · · · · · · · · · · · · · · ·		5.57	0.0474	
24					5.31	0.0623	
25					5.71	0.03	
26	3.2	1750	15.6		5.82	0.03	
27					6.4	0.039	
28	AA		22.8	1.27	6.49	0.0438	·
29					6.6	0.0468	
30					6.75	0.0632	
31			· · · · · · · · · · · · · · · · · · ·		6.23	0.0565	
)TAL	6	1753	83.6	1.47	189.2	1.4062	0
VG	0.75	6.4678	10.45	0.735	6.1032	0.0454	
iΑΧ	3.2	1750	22.8	1.27	6.75	0.07114	
/IN	0	1	2.4	0.2	5.24	0.0161	
	l		· -	- · -			


dditional Remarks:

I certify under the penalty of law that I have personally examined and am familiar with the information submitted and based on my inquiry of those individuals immediately responsible for obtaining the information, I believe the submitted information is true, accurate and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment.

m No EPA 4500 (8-91)

ETHER SURI

Date Report Completed: 09/19/2001



Title of Reporter: ARWWP PROJECT MANAGER

ame, Address City, County, ZIP: mald Environmental Management Project

Station Code:

Reported Date (Month Year):

Application:

09/19/2001

August 2001

.

-

00 Willey Road amilton OH 45013940

Sampling Station Description:

UPSTREAM MONITORING - UPSTREAM OF OUTFALL 11000004001

Page 1 of 3

3883

1) - E	nter 1 for Continuou	us, 2 for Composite,	3 for Grab Sample	Reporting Lab:		Analyst:	
2) - E	nter frequency of sa	ampling					
(4)	3	3	T				
(1)	3	1	3	3	3	3	3
(2)	(00900)	(00400)	(00010)	1 (22222)	1 (20512)	1 (22252)	(01055)
	Hardness, Total	ДH	Water Temperature	(00300) Dissolved Oxygen	(00610) Nitrogen, Ammonia	(00979) Cobalt, Total	Manganese, Total
ay	(CaCO3)	s.u.	С	mg/l	(NH3)	Recoverable	(Mn)
11	mg/l AH	АН	AH ·	AH	mg/1 AH	ug/l AH	ug/l AH
2		741	- All	An		An	An
3							
4						·	
5					 		
6	•						
7					†		
8		•					
9						·	
0							
1	•						
2							
3							
4			·				1
5							
6						·	
7		,, <u></u>					
8							
9							
0			·				
1							
2				······································			
3							
4							
5					· · · · · · · · · · · · · · · · · · ·		
6							
7							
8		· !					
9							
0			1				
1							
ΓAL	0	0	0	0	0	0	0
/G	0	0	0	0	0	0	0
ax l	0	0	0	0	0	0	0

dditional Remarks:

0

ΛIN


MPLES WERE NOT COLLECTED DUE TO MANPOWER ISSUES. SAMPLES WILL BE COLLECTED IN SEPTEMBER 2001.

I certify under the penalty of law that I have personally examined and am familiar with the information submitted and based on my inquiry of those individuals immediately responsible for obtaining the information, I believe the submitted information is true, accurate and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment.

rm No EPA 4500 (8-91)

COMPLETE SERVE SURI

Date Report Completed: 09/19/2001



NTHLY REPORT FORM

4500

me, Address City, County, ZIP: ald Environmental Management Project Station Code:

) - Enter 1 for Continuous, 2 for Composite, 3 for Grab Sample Reporting Lab:

Reported Date (Month Year):

Application:

09/19/2001

) Willey Road nilton OH 45013940 801 August 2001 11000004*FD

Analyst :

Sampling Station Description:

UPSTREAM MONITORING - UPSTREAM OF OUTFALL 11000004001

Page 2 of 3

3883

- Er	nter frequency of s	ampling					
1)	3	3 .	3	3	3	· 3	3
2)	1	1	1	1	1 .	1	1
	(01074) Nickel, Total Recoverable ug/l	(01079) Silver, Total Recoverable ug/l	(01094) Zinc, Total Recoverable ug/l	(01113) Cadmium, Total Recoverable ug/l	(01114) Lead, Total Recoverable ug/l	(01118) Chromium, Total Recoverable ug/l	(01119) Copper, Total Recoverable ug/l
	AH	AH	AH	AH	AH	AH	, AH
7							
1							
†							**************************************
†					<u> </u>		
†							
+							
+							
+							
+							
+							
+							
+							.i
1							
1							
1							
1					•		
			•				
T							
T		· ·					,
T							
†			· · · · · · · · · · · · · · · · · · ·				
+				,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,			
+	····						
+	——————————————————————————————————————	·					
+							
+							
+	*						······
+							
+							
1							
+							·
+		0					0
1	0		0	0	0	0	<u> </u>
1	0	0	0	0			0
+	0	0	0	0	0	0	0
	ν		U	U	U		· U

ditional Remarks:

PLES WERE NOT COLLECTED DUE TO MANPOWER ISSUES. SAMPLES WILL BE COLLECTED IN SEPTEMBER 2001.

NTHLY REPORT FORM	٨.
-------------------	----

00 Willey Road

milton OH 4501394(

ame, Address City, County, ZIP: nald Environmental Management Project

Station Code:

Reported Date (Month Year):

Application:

09/19/2001

801

August 2001

11000004*FD

.

Sampling Station Description:

UPSTREAM MONITORING - UPSTREAM OF OUTFALL 11000004001

Page 3 of 3

) - E	nter 1 for Continuo	ous, 2 for Composite,	3 for Grab Sample	Reporting Lab :		Analyst:	•
) - E	nter frequency of s	sampling					
						<u> </u>	
(1)	. 3	1					
(2)	1		·				
İ	(99992) Mercury, Total						
	Mercury, Total Recoverable ug/l						
ay	ug/1						
1	AH	<u> </u>					
2							
3	······						
4							
5	, , , , , , , , , , , , , , , , , , ,						
6							
7					,		·
8							
9							
0							
1			:				
2							
3							
4				• .			
5							
6	.* .						
7	,						
8							<u> </u>
9					,		
0					,		1
1							
2		, , , , , , , , , , , , , , , , , , ,					
3							
4							
	- P						
5							·
6	,						
7	· · · · · · · · · · · · · · · · · · ·						
8				<u> </u>			
9							
0						Á	
1							
AL	0	0 .	0	0	0	0	0
'G							
X N	0						
N	0						

Iditional Remarks:

IPLES WERE NOT COLLECTED DUE TO MANPOWER ISSUES. SAMPLES WILL BE COLLECTED IN SEPTEMBER 2001.

amilton OH 45013940

4500

lame, Address City, County, ZIP: ernald Environmental Management Project 100 Willey Road

Station Code:

Reported Date (Month Year): · August 2001

DOWNSTREAM - NEARFIELD MONITORING - DOWNSTREAM OF OUTFALL 11000004001

Application:

09/19/2001

902

Sampling Station Description:

1I000004*FD

Page 1 of 3

3883

ŧ		
(1) - Enter 1 for Continuous, 2 for Composite, 3 for Grab Sample	Reporting Lab :	Analyst:
(2) - Enter frequency of sampling		

(1)	3	3	3	3	3	3	3
(2)	1 .	1	1	1	1	1 .	1
Day	(01094) Zinc, Total Recoverable ug/l	(01113) Cadmium, Total Recoverable ug/l	(01114) Lead, Total Recoverable ug/l	(01118) Chromium, Total Recoverable ug/l	(01119) Copper, Total Recoverable ug/l	(01055) Manganese, Total (Mn) ug/l	(01074) Nickel, Total Recoverable ug/l
01	AH	AH	AH	AH .	AH .	AH	AH .
02							
03		·					
04							
05		· · · · · · · · · · · · · · · · · · ·					
06							
07							-
08					•		
09							
10			·			,	·
11							
12							
13							
14							
15							
16			·				
17							
18							
19		· .					
20 21				<u>-</u>			
22					· · · · · · · · · · · · · · · · · · ·		
23							
24							
25		· · · · · · · · · · · · · · · · · · ·			,		
26				,			
27					· · · · · · · · · · · · · · · · · · ·		
28							
29							
30							
31							
OTAL	0	0	0	0	0.	0	0 . ·
AVG	0	0	. 0	0	0	0	0
MAX	· 0	0 .	0	0	0	0	0
MIN	0	0	0	0	0	. 0	0

Additional Remarks:

AMPLES WERE NOT COLLECTED DUE TO MANPOWER ISSUES. SAMPLES WILL BE COLLECTED IN SEPTEMBER 2001.

I certify under the penalty of law that I have personally examined and am familiar with the information submitted and based on my inquiry of those individuals immediately responsible for obtaining the information, I believe the submitted information is true, accurate and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment.

orm No EPA 4500 (8-91)

pomerty FRA SURI

Date Report Completed: 09/19/2001



Title of Reporter:

ARWWP PROJECT MANAGER

amilton OH45013940

lame, Address City, County, ZIP: ernald Environmental Management Project 100 Willey Road

Station Code:

Reported Date (Month Year):

Application:

09/19/2001

902

(1) - Enter 1 for Continuous, 2 for Composite, 3 for Grab Sample Reporting Lab:

August 2001

1I000004*FD

Sampling Station Description:

Page 2 of 3

DOWNSTREAM - NEARFIELD MONITORING - DOWNSTREAM OF OUTFALL 11000004001

(1)	3 .	3	3	3	. 3	3	3
(2)	.1	1	1	1	· 1	1	1
ıy	(01079) Silver, Total Recoverable ug/l	(00900) Hardness, Total (CaCO3) mg/l	(00610) Nitrogen, Ammonia (NH3) mg/l	(00010) Water Temperature C	(00300) Dissolved Oxygen mg/l	(00400) pH S.U.	(99992) Mercury, Total Recoverable ug/l
1	AH	AH `	AH	АН	AH ·	АН	АН
2					· · · · · · · · · · · · · · · · · · ·		
3							
1					·····		
5							
3			-				
7					······································		
В							
9							
0							
1							
2	,						
3						***************************************	
4							
5							ļ
5	· · · · · · · · · · · · · · · · · · ·	<u> </u>					
7							
3	1-11-11-1						
)			,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	· · · · · · · · · · · · · · · · · · ·		***************************************	
,				•	·		
,					· 	·	
2				·			
3							
1							
5						•	
5							
7			***************************************	····			
3			···········				
)							
).							
AL	0	0	. 0	0	0	0	0
G				 -		7.	-
X	0	0	0	0	0	0	0
N	0	0	0	0	0	0	0

dditional Remarks:

AMPLES WERE NOT COLLECTED DUE TO MANPOWER ISSUES. SAMPLES WILL BE COLLECTED IN SEPTEMBER 2001. Name, Address City, County, ZIP:

Fernald Environmental Management Project

7400 Willey Road Hamilton OH45013940 Station Code: 902

Reported Date (Month Year):

August 2001

Application:

09/19/2001

1I000004*FD

Page 3 of 3

Sampling Station Description:

DOWNSTREAM - NEARFIELD MONITORING - DOWNSTREAM OF OUTFALL 11000004001

) - Enter 1 for Continuous, 2 for Composite, 3 for Grab Samp) - Enter frequency of sampling			Reporting Lab :		Analyst :	
11(2) - 61							
(1)	3					-	
(2)	1						
D-11	(00979) Cobalt, Total Recoverable						
Day	ug/1						
01	НА						
02			·				
03		,					
04							
05							
06							
07							
80					·		
09							
10							
11					· · · · · · · · · · · · · · · · · · ·	,	
12							
13							
14				-		,	
15	······································						
16							
17							
18							
19							
20				· · · · · · · · · · · · · · · · · · ·			
21	'a 'a ' 						
22					,		
23							
24	.						
25							,
26	· · · · · · · · · · · · · · · · · · ·						
27							
28							
	i						
29						<u> </u>	
30	<u> </u>					<u> </u>	•
31							:
TOTAL	0	0	0	0	0 .	0	0
AVG	,						
MAX	0						
MIN	0 (·				

Additional Remarks:

SAMPLES WERE NOT COLLECTED DUE TO MANPOWER ISSUES. SAMPLES WILL BE COLLECTED IN SEPTEMBER 2001.

Harootyan, Brian

From: Sent:

Subject:

Harootyan, Brian

Wednesday, September 19, 2001 3:55 PM 'SWIMWARE@WWW.EPA.STATE.OH.US'

3883

To: Cc:

Brettschneider, David; Hertel, William; Johnston, Frank; Nickel, Kathi; Harootyan, Brian

August 2001 Discharge Monitoring Reports



Attached are the electronic submittals of the August 2001 DMR's.

If you have any questions, please contact Brian Harootyan at (513) 648-4202.

Harootyan, Brian

From: Sent:

Web Mail Admin [daemon@demboy.epa.state.oh.us]

Thursday, September 20, 2001 12:35 PM

Brian.Harootyan@fernald.gov To:

3883

Ohio EPA - Electronic Data Submission Receipt

System: SWIMWARE Version: 1.0.0

Fernald Environmental Management Project

7400 Willey Road

Hamilton OH 450139402

(513)-6484202

The following file was received on Thu Sep 20 12:35:15 2001 Email attachment(s):

15433851.ZIP (application/octet-stream)

If you have any questions regarding this receipt or your data transmission, please call the SWIMware Help Line at: (614) 644-2050 or send e-mail to: jeffrey.boyles@epa.state.oh.us.